

Head Office - Australia

5 Grace Court, Sunshine VIC 3020 **T.** (03) 9312 2177 ABN. 99 006 152 932



PLT FIRMWARE UPGRADE - SERIES-II

Version 4.02.07







Version 5.00.09

Current as at 20-05-2019





Firmware upgrade is embedded on the SD Card.

To Upgrade firmware:

- Switch power of to controller
- Remove existing SD card and place new one in
- Switch power back one
- Upgrade will take place.. "DO NOT REMOVE SD CARD OR SWITCH OFF POWER DURING THIS PROCESS"

Discard old SD card and leave new one in controller, this is now registered as the new one to use for this controller.

Note: The existing controller serial number is retained.

FIRMWARE UPGRADE COST \$ 35.00 + GST & Shipping. PER CONTROLLER (SD CARD)

NOTE: OPERATION BETWEEN SERIES-II Version 4 and 5 NOT RECOMMENDED DUE TO HARDWARE AND FIRMWARE INCOMPATIBILITY DIFFERENCES.

SERIES-I CONTROLLERS (YELLOW METAL ENCLOSURE TYPES) ARE CONSIDERED LEGACY AND REPLACEMENT RECOMMENDED – FUNCTIONALY FOR THESE IS ONLY MASTER-SLAVE AS A SET